Site Characterization & Forensic Geochemistry



Quality Systems for Hydrocarbon Analyses: Similarities and Differences between EPA, ASTM and GPA methods – Considerations for a more Unified Approach

November 9, 2016 IPEC - NOLA



David A. Gratson, CEAC Michael R. Green, Ph.D. Rock J. Vitale, CEAC Environmental Standards Inc.

W. James Bover, Ph.D., WJB Consulting LLC

J. Andrew Tachovsky, P.E., Sabine River Partners

Agenda



Flash Gas Emission Estimates (e.g. Section 114 "request" of E&P operators)

Analysis of pressurized sample (condensate, oil, wa ter) e.g. CARB Appendix B*


> Methods include ASTM (e.g. D2597); GPA (e.g. 2177, 2286); and U S EPA (e.g. Method TO-15, 8260)

ASTM, EPA, GPA all cited

*Regulation for the Mandatory Reporting of Greenhouse Gas Emissions , California Air Resources Board 2013 Appendix B: Flash Emissions of Greenhouse Gases and Other Compounds from Crude Oil and Natural Gas Separator and Tank Systems EPA, ASTM, and GPA all have separate QC Practices

3

Elements of a Quality System



Quality System Terms Within Systems


EPA: Blank, LFB/LCS, Duplicates, Matrix Spikes, PE Sample, Surrogates, Internal Standards

GPA: Repeatability, Reproducibility, Reference standard blend, Linearity Plot, Fidelity Plots

ASTM: Repeatability, Reproducibility, SQC, check standard, internal standards, proficiency test samples, verification samples, CRM

Shall/Should/Recommend; Incorporation by Reference

GPA Quality Practices




US EPA Quality Practices

Method (Program) specific QC

Proficiency Testing required with some programs & state accreditation

RCRA includes performance-based allowances



US EPA Quality Practices

Consider Methods 8260 and

TO-15 (cited by CARB)

Batch Quality Control

- Daily calibration
- Blank (negative control)
- Internal Standards/Surrogates
- Sensitivity (MDL, RL)
- Precision (duplicates) & Accuracy (check stds) assessment
- Qualitative Criteria
- Method Performance Information (no required use)
 - Single and multi-laboratory precision and accuracy

The NELAC Institute

Environmental Laboratory Sector - Technical Requirements (2009)

- Quantification formulae
- Qualitative/selectivity
- Constant/reproducible test conditions
- Reagents and standards quality
- Calibration
- Measurement traceability
- Batch Quality Control
 - Positive & negative control
 - Precision
 - Accuracy
 - Sensitivity (RL, MDL)
- PT Studies for Accreditation

ASTM Quality Practices – D2

D6792 QA System– Technical Requirements

- Calibration (test method specific) & Verification (CRM)
- Quality Control Practices
 - Control charts, per D6299
 - Accuracy, precision
 - "Regular" analysis of QC samples (9%, then per TPI & PT results)
 - QC expressed as both repeatability & reproducibility
 - QC sample: stable/homogeneous/similar to samples

ASTM Quality Practices – D2

D6792 QA System– Technical Requirements

- Repeatability: single operator, instrument, back to back
- Reproducibility: between laboratories (personnel + instruments)
- Test Performance Index (TPI): compare laboratory precision with published reproducibility
 - TPI = <u>Test Method</u> reproducibility/site precision Lab precision should be better than inter-laboratory reproducibility

ASTM Quality Practices System – D2


D6299 Statistical Quality Assurance and Control Charting Techniques to Evaluate Analytical Measurement System Performance

- Provides practices for quality control and control charting
 - Reference Material Analysis
 - Stability and Precision QC Testing
 - Accuracy Monitoring
 - Charting Proficiency Testing Data
 - Periodic, Independent System Validation (Validation Audit)

12


ASTM D6299 and 40 CFR (EPA), GPA

- ASTM D6299 was incorporated by reference into parts of 40 CFR (*e.g.*, 80.47). As such, compliance with both ASTM D6299 and 40 CFR 80.47 may expect to generate the same statistical evaluations:
- I charts
- Outlier evaluation




ASTM D6299 - continued

- Moving range charts
- Outlier evaluation



ASTM D6299 - continued

+ Q/Q Chart (setup data); Anderson-Darling: 0.868 (RMS), 0.857 (MR)



Control Charting: ASTM D6299 and GPA 2198

- GPA 2198 speaks to the same types of control charting practices as D6299, although with less specificity. Example
 - I charting is explicit in D6299, implied in GPA 2198
- Other aspects of ASTM D6299 control charting that are not addressed in GPA 2198:
 - Normality assessment
 - Moving range chart preparation
 - Pre-treatment of results
 - F-test for similar variances and t-test for means
 - Methods for identifying outliers
 - Calculation of trend
 - Transition to next QC material (e.g., Q-procedure)
 - ASTM allows use of <u>EWMA</u> run rules

Cross Program Practices

	EPA	GPA	ASTM
Calibration	Initial and ongoing with method defined criteria	Calibration plots for "linearity", Fidelity plots	Test method specific. Initial/on-going typical
Negative Control	Field, laboratory blanks compared sensitivity limits	Not discussed	Blanks in some methods
Accuracy Control (calibration)	Calibration verification check standard	Nothing equivalent for bias	Check Standard
Accuracy Control (surrogate/IS)	Surrogates, internal standards	Nothing equivalent	Internal standards in some methods
Accuracy Control (matrix spike)	Matrix spike	Nothing equivalent	Nothing equivalent
Accuracy Control (PT)	PT	Control charts	Control charts, SQC of reference material, inter- laboratory cross check

Cross Program Practices

	EPA	GPA	ASTM
Precision Control (samples)	Batch duplicates (samples, spikes), RPD criteria in methods or lab derived	Daily sample duplicates, repeatability criteria in methods	SQC of samples, repeatability and reproducibility criteria in methods
Precision Control (standards)	Nothing equivalent	Daily calibration standard duplicate, reproducibility criteria in methods	SQC of reference material, repeatability and reproducibility criteria in methods

Hydrocarbon Testing Unification

	ASTM	GPA	Tier III (EPA)
Embedded QC Practices -control charting -check standards - positive & negative controls -internal standards -surrogates	Surrogates NA	 Not included: Internal Standards negative controls Surrogates 	
Reference to a specific petroleum lab quality system practices		None	None within EPA methods
Specific/strict initial calibration requirements		None	
Interlaboratory accuracy/precision checks			None
PT/SRM Program			Within some programs ¹⁹

Thank You



Headquarters 1140 Valley Forge Road | PO Box 810 | Valley Forge, PA 19482 | 610.935.5577
Virginia 1412 Sachem Place, Suite 100 | Charlottesville, VA 22901 | 434.293.4039
Tennessee 8331 East Walker Springs Lane, Suite 402 | Knoxville, TN 37923 | 865.376.7590
New Mexico PO Box 29432 | Santa Fe, NM 87592 | 505.660.8521
Illinois PO Box 335 | Geneva, IL 60134 | 630.262.3979
Web www.envstd.com | E-mail solutions@envstd.com